WELCOME TO 1352 Bitter Lake Road *Bitter Lake*





Annual Costs

- ➢ Hydro One = \$1,240.56 (2024)
- Propane Cost for Fireplace = \$480 (2024)
- Propane Tank Annual Fee \$339.00
- Property Tax Bill = \$2,204.68 (2024)



Schedule "C"

Inclusions/Exclusions List

1352 Bitter Lake Road, Bitter Lake

INCLUSIONS

Everything as viewed in/outside cottage and bunkie except what is noted in <u>EXCLUSIONS</u> below


EXCLUSIONS

Cottage

Dresser, end table, rocking chair & lamp in Primary Bedroom Living Room Cabinet, wall unit shelf, stereo and tv, tv stand Kitchen round end table on wheels by sitting chair Black umbrella in the dining table on the deck Sunroom/bedroom blanket box, lamps and 2 end tables Bunkie chair and table 2 wicker chairs and table on deck in front of bunkie BBQ and old table on side deck in front of bunkie All paddle boards and kayaks 4 Muskoka type chairs Log splitter and small utility trailer All wall hangings > All art **Buyers** Initials Seller's Initials

Schedule "D" – Survey

LOT 41, PLAN 404, Dysart et al



Seller's Initials

Sewage Installation Report

1352 Bitter Lake Road, Bitter Lake

HKPR
SEWAGE SYSTEM INSTALLATION REPORT
REPORT DATE NOUSMARCH 02/01
INSTALLED BY
Septic Tank/Holding Tank of working capacity of Jord Intres constructed of steel/concrete/fibreglass, Manufacturer
- Distribution Pipe. Type Absorption Trench System
Filter Bed System @ Filter Bed Area _ 17 sq. m., Contact Area _ 17 sq. m.
Total Lineal Metres in runs of 3.5, metres and fed by gravity, Siphon; or Pump
Area of Building: $\underline{-2\omega} m^2$ $\underline{-2\omega} F_{RUU} F_{RUU} \sigma^2$
Actual location and orientation of components of sewage system are shown hereunder above as outlined on the Site Inspection Report For A Sewage System form
111111111111142.SIX13181111111201111111201
╘┼┼╢┼╎┲┾╢┇╗╪╪┼┿┽┼╎╎╎┾┼╎╎╎┼┲┼╎╎╎┼┲╪┽╎┊╶ <mark>╧╴┿┿</mark> ╶┼┽┼╏┆┥┿┽┼┾┼┾┼┆╎╎┾┾┿┿╹ <mark>╎</mark> ╱┾┿┇╎╎┾┾╇┼┼┊
┝┲┶┥╢╶┸┲┶┽┥╀╶┇┙╪╪┼┼┼╡╡┫┥┼╡╎╌┽┽┽┥┨╝╡╴┼┝┝╡┼╵╧╘┙╡┼┼┨┙╼╲ <u>┥┍╖╦┿┿╼┾╪┿╼╪</u> ╋┍╲╲ <mark>╧╢</mark> ╞┽╎┾╄╞┽┼┼┼┼┼┼┼╴
╈┙╢┼┿┿┽┼┇┽┽┼╏┾┽┼╎┼╏┠┼┼┇┊┼┼╽┠╗╎┼┾┿┽┼┊╧╗┼┼┦┨╴ <mark>┿┿╎┿┽┝┿┝╋╢┾┿┝╋╹┼╦┼┍╴</mark> ╢╗┿┼╎┼┼╎┼┼┼┼┼┼┼
┿┽╢╴┼╴╪╱┝╧╎┾╎┥┝┝┽┥┊╕╕╏┝┼╶┙╕┑┥┥╢╎╎╴╎╴┥┥┙╎╎╎╶┝╎╎╺┿╌╴╸┍╖╢╸╛╸┥╸╽╻┼╍┝┥╖┙┙╸┙╸┙╸┙╸╸╸╸╸╸╸╸╸╸╸╸╸╸╴╴╸╸╴╴╴╴╴╴╴╴╴╴╴╴
The following work remains to be completed Backfull system and sod or seed 🗄. Stabilize all sloped surfaces 🖶. Finish grading to shed run-off and divert water
around leaching bed Drother <u>Completer</u> ALGRAM - Pump INSTALL ARTON
CONNECTION TO NYDRO PONER
INSTALLATION REPORT
Under the Building Code Act and regulations and subject to the limitations thereof, a permit is hereby issued to SUSAN FROT, TRACY GREEN
For the use and operation of the Class Sewage System Installed / Altered under Site Inspection Report # Gura 31-07.
Such system being located on Lot 16, 190nc. 10 Plan 404 Sub. lot 4/ Roll No.
Township / County / City Guil Ford Have our former gency # 911 Emergency # 911 F
(Appointed Inspector - Part 8)
Date Neverber at Zcrel issued - Com all
(Designated Seivage Inspector - Part 8)

NOTE: No change can be made to any building(s) or structures in connection with which this sewage system is used, if the operation or effectiveness of the sewage system will be affected by the change, unless a Site Inspection Report is obtained.

.

Septic Pumping Invoice

Eag	n Septic Pumping Box 158 le Lake, On 0M 1M0 pticpumping@live.ca t 809254147	DATE TAX REG. NO. Nº DE TAXE ORDER NO. Nº DE COMMAN		121	
ENDUA Stev	e Murph	Y			
DRESS DRESSE	352 BiHer	Lake Rd.		1	
RPÉDIER À BI	Hen Lake	AUT	18 4		1
DDRESS DRESSE	647-298-	2008	-	25.	i)
IPPING DATE VIA	TERMS	BUYER	S	OLD BY	1.30
ATE D'EXPÉDITION	CONDITION	S ACHETEUR	V	NDU PAR	
QUANTITY QUANTITÉ	DESCRIPTION		PRICE PRIX	AMO MON	UNT TANT
1	1 1 1 1 m		1. 1	a Y	-
3	und ant s	Senti.		200	
4	The second	The second state	a Vid	2. 19	
5				6.62	
6		01		13.5 7	
8	VIC	() L.	/	101	
9	Montral	1 Not	13/	2(N.
10	T pe		- (
12	10001				-
	me Dock	-			
13 0	a second and a second se		TVH/HST TPS/GST	26	-
13 US 14	0				
	~ 3 year		TOTAL	226	

Improvements


- Wood burning airtight stove
- Docking system
- Septic system
- All landscaping
- Metal roof
- Upgraded electrical to 100 amp
- Enlarged parking area
- Resided exterior
- Reinforced decking
- Rebuilt main decking including new railings
- New side deck and stairs to the lake
- Bunkie (2023)
- Interior and exterior painting
- Built large woodshed
- All new windows
- Removed door and added new windows in sunroom







Lake Location Map



Area Map

